

## KC Warford Transmission

### Engine RPM at Selected Speeds

<b>Ford High Warford Low</b>		<b>Ford High Warford 2nd</b>		<b>Ford High Warford High</b>		
<b>3.63 : 1</b>		<b>3.63 : 1</b>		<b>3.63 : 1</b>		
Ring Gear		Ring Gear		Ring Gear		
3 : 1*		3 : 1*		3 : 1*		
<b>MPH</b>	<b>Engine RPM</b>		<b>Engine RPM</b>		<b>Engine RPM</b>	
5	<b>377</b>	310	<b>206</b>	169	<b>171</b>	140
10	<b>753</b>	621	<b>411</b>	339	<b>341</b>	281
15	<b>1131</b>	931	<b>617</b>	508	<b>512</b>	421
20	<b>1506</b>	1242	<b>822</b>	678	<b>682</b>	563
25	<b>1884</b>	1552	<b>1028</b>	847	<b>853</b>	703
30	<b>2261</b>	1864	<b>1234</b>	1017	<b>1024</b>	844
35	<b>2637</b>	2173	<b>1439</b>	1186	<b>1194</b>	984
40	<b>3014</b>	2485	<b>1645</b>	1356	<b>1365</b>	1125
45	<b>3390</b>	2794	<b>1850</b>	1525	<b>1535</b>	1265
50	<b>3767</b>	3104	<b>2056</b>	1694	<b>1706</b>	1405
55	<b>4145</b>	3416	<b>2262</b>	1864	<b>1877</b>	1547
60	<b>4521</b>	3725	<b>2467</b>	2033	<b>2047</b>	1687
65	<b>4898</b>	4035	<b>2673</b>	2202	<b>2218</b>	1827

1800 RPM is considered to be RED LINE. Red line on your engine will depend on components you have installed.

\* We DO NOT recommend the use of a 3:1 high speed ring & pinion gear unless you have both a very light weight car and a very strong engine with a high compression head.